**बैंक अधिकारियों के विरुद्ध केन्द्रीय जांच ब्यूरो की जांच**

2548. **श्री नागमणि:**
**श्री कनकसिंह मोहनसिंह मंगरोला:**

क्या **प्रधान मंत्री** यह बताने की कृपा करेंगे कि:

(क) उन अधिकारियों के नाम क्या-क्या हैं, जिनके विरुद्ध केन्द्रीय जांच ब्यूरो ने पिछले तीन वर्षों के दौरान जांच की तथा उक्त जांच किन-किन तिथियों को आरंभ की गई तथा ऐसे कितने मामलों के संदर्भ में जांच पूरी हो गई है;

(ख) इस जांच के क्या परिणाम निकले तथा उन अधिकारियों के नाम क्या-क्या हैं, जिनके विरुद्ध केन्द्रीय जांच ब्यूरो ने कार्रवाई किए जाने की सिफारिश की है; और

(ग) उन अधिकारियों के नाम क्या-क्या हैं, जिनके विरुद्ध सरकार द्वारा कार्रवाई की जा चुकी है तथा की गई कार्रवाई का ब्यौरा क्या है?

**कार्मिक, लोक शिकायत और पेंशन मंत्रालय में राज्य मंत्री (श्री एस०आर० बालासुब्रहमण्यन)** (क) से (ग) वित्त मंत्रालय द्वारा सूचना एकत्रित की जा रही है और उक्त मंत्रालय इस विषय में सदन को सूचित करने के लिए सहमत हो गया है।

**Flaws in Nuclear Installations**

2549. SHRI SOLIPETA RAMACHANDRA REDDY: Will the PRIME MINISTER be pleased to state:

(a) the major flaws in nuclear installations listed by the Atomic Energy Regulatory Board in its recent Report; and

(b) the steps taken to stop leakage of radio activity from nuclear installations, especially at Bhabha Atomic Research Centre?

THE MINISTER OF STATE OF THE MINISTRY OF PLANNING AND PROGRAMME IMPLEMENTATION AND MINISTER OF STATE OF THE MINISTRY OF SCIENCE & TECHNOLOGY (SHRI YOGINDER K. ALAGH): (a) The major areas of possible safety upgradation identified by the AERB include desirable improvements and modifications in the emergency core-cooling systems of reactors, further evaluations and in-depth inspection of Zircalloy Pressure Tubes in PHWs for their integrity, improvements which could further reduce the collective radiation exposure to occupational workers, means to lower the potential for leakage from radioactive waste management systems, the evaluation of structural response to earthquake forces in some of the facilities, and preventive measures related to fire safety and flooding.

(b) The acutal radioactivity releases by way of gaseous and liquid effluents from the nuclear power plants are controlled and are far below the permissible limits stipulated by AERB. Radioactive liquids are stored in BARC installations in underground stainless steel tanks and are engineered to have a very high standard of integrity. The tanks are located in a vault which serves as a secondary container. The inner surface of these vaults are lined with stainless steel plates. Monitoring wells are provided in the vicinity of the storage facilities to sample ground water in the area. The engineered design features and monitoring procedures ensure that radioactive liquids do not leak into the environment.

**Posting of women Government servents at the work place of their Husbands**

2550. SHRI BHUPINDER SINGH MANN: Will the PRIME MINISTER be pleased to state:

(a) whether there are instructions that women Government servants married to Government servants may be posted at the place of work of their husbands as far as possible;

(b) if so, whether women government servants are denied posting at the places of work of their husbands on the plea of administrative grounds manipulating the work "as far as possible"; and

(c) if so, what steps are being taken/would be taken by Government to remove this lacunae?